



Pull EN above 1.35V to turn the device ON.
For automatic enable, connect to VIN using

PROJECT: DRAWING TITLE: DRAWN BY:		PS-Meter v1 	REVISION
SHEET: 1 OF 1			A
DATE: 2016/7/25		2014 imAkichi / cycle.eek.jp	